

Ф30.8 **SR927W**

Chronograph

Small Second

7 Date

12 Chronograph

60

Chronograph Hour Minute


Clearance

Balance

Weight

<µN.m>

Clearance changes subject to the glass, case structure, and the length of the hand.



Chrono Second 0.11

Featured by Shock Detection

Minute 0.40

Small 0.02

Original Package

500pcs


0S11 **0S10** 12 7 High Hand Ver. 0S1A 0S1F

Time measurement

Accuracy

The unit (gate) time of measurement must be set at "10 sec." and the measurement must be performed in the form of complete watch.

10 sec 10 sec 10 sec



Reset the chronograph

Setting the Time

Set CHRONOGRAPH hands to reset

Push A to reset the hands position to the ZERO position, And continue to push A to put them forward