

<b>Size</b> <ligne>	10 ½”
<b>Height</b> <mm>	5.10
<b>Accuracy</b> <per Month>	±20 sec
<b>Battery Life</b>	2 years

\*60 minutes chronograph operation per day



Battery consumption could be minimum by pulling out the stem

<b>Balance Weight</b> <µN.m>	Minute 0.40 Chrono Second 0.08 Small 0.02
---------------------------------	---

Featured by Shock Detection

<b>Clearance</b>	<p>Hand ↔ 0.30-0.45mm. ↔ case Movement ↔ 0.20-0.45mm.</p>
------------------	---

<b>Original Package</b>	500pcs
-------------------------	--------




High Hand Ver.  
FS13  
FS23

## Time measurement

### Accuracy

The unit (gate) time of measurement must be set at "10 sec." and the measurement must be performed in the form of complete watch.



**Push "A"**  
Start and Stop the chronograph

**Setting the Time**

**Set CHRONOGRAPH hands to reset**

Push A to reset the hands position to the ZERO position.  
And continue to push A to put them forward

**Push "B"**  
Reset the chronograph

**Setting the Date**

DQ NOT set Date between  
9:00pm - 1:00am