
FS16 FS26

MIYOTA



Battery consumption could be minimum by pulling out the stem


Minute 0.40

Veight
Chrono Second 0.08
Small 0.02

Featured by Shock Detection

Clearance

Clearance changes subject to the glass, case structure, and the length of the hand.



Original Package

500pcs

Time measurement

Accuracy

The unit (gate) time of measurement must be set at "10 sec." and the measurement must be performed in the form of complete watch.

10 sec 10 sec 10 sec



7













our Small Second





Push "B"

Reset the chronograph

Setting the Time and Dualtime hands (local time)

Set CHRONOGRAPH hands to reset

Push A to reset the hands position to the ZERO position, And continue to push A to put them forward

Setting the Date and Home time hour hands

DO NOT set Date between 9:00pm – 1:00am