
## JS00 JS10 JS20 JS50 JS55

# **MIYOTA**



#### Battery consumption could be minimum by pulling out the stem

**Balance** Minute 0.40Weight <µN.m> Second 0.09 Small 0.02

### Featured by Shock Detection

#### Clearance Clearance changes subject to the glass, case structure, and the length of the hand.

case 0.30-0.45mm. Movement \$ 0.15-0.65mm.

## **Original Package**


500pcs

#### Time measurement

#### **Accuracy**


The unit (gate) time of measurement must be set at "10 sec." and the measurement must be performed in the form of complete watch.


10 sec 10 sec 10 sec



Chronograph Second

Chronograph





Setting the Date

Set CHRONOGRAPH hands to reset

Push A to reset the hands position to the ZERO position, And continue to push A to put them forward