



High Hand Ver. 2117

Battery consumption could be minimum by pulling out the stem



Featured by Shock Detection



Time measurement

Accuracy

The unit (gate) time of measurement must be set at "10 sec." and the measurement must be performed in the form of complete watch.



