

ΠΙΥΟΤΑ

Time measurement & Winding


Mechanical

Accuracy

Measure within lapse of $10 \sim 60$ minutes from full winding with (1) posture.

Posture difference

Measure accuracy in below $(1) \sim (4)$ postures.



To make full-winded

90/91	Turn the crown 40 times
82 / 8N	Turn the crown 40 times
6T	Turn the crown 20 times

Winding direction

