



## 2070



## Battery consumption could be minimum by pulling out the stem



## Time measurement —

## Accuracy

The unit (gate) time of measurement must be set at "10 sec." and the measurement must be performed in the form of complete watch.

10 sec 10 sec 10 sec

