


JS05 JS15 JS25

MIYOTA



500pcs






Time measurement

Accuracy

Original Package

The unit (gate) time of measurement must be set at "10 sec." and the measurement must be performed in the form of complete watch.

10 sec 10 sec 10 sec



Reset the chronograph

Setting the Time

Set CHRONOGRAPH hands to reset

Press the button "A" to set the stopwatch second hand forward.

Press the button "B" to set the stopwatch second hand back.

DO NOT set Date between 9:00pm - 1:00am