



Time measurement & Winding

Mechanical


Accuracy

Measure within lapse of 10 ~ 60 minutes from full winding with ① posture.

Posture difference

Measure accuracy in below ① ~ ④ postures.

- ①Dial side up
- 26 o'clock side up
- 39 o'clock side up
- 43 o'clock side up



■ To make full-winded

| 90 / 91 | Turn the crown 40 times |
|---------|-------------------------|
| 82 / 8N | Turn the crown 40 times |
| 6T | Turn the crown 20 times |

■ Winding direction



