

JS00 JS10 JS20


Size <ligne>	12 ½"
Height <mm>	4.13
Accuracy <per Month>	±20 sec
Battery Life	3 years

*30 minutes chronograph operation per day



Battery consumption could be minimum by pulling out the stem

Balance Weight <μN · m>	Minute 0.40 Second 0.09 Small 0.02
----------------------------	--

Featured by Shock Detection

Clearance	 <p>Hand \updownarrow 0.45mm min. Movement \updownarrow 0.15 ~ 0.65mm</p>
-----------	--

Original Package	500 pcs
------------------	---------



Time measurement

Accuracy

The unit (gate) time of measurement must be set at "10 sec." and the measurement must be performed in the form of complete watch.



Push "A"
Start and Stop the chronograph

Setting the Time

Set CHRONOGRAPH hands to reset

Push A to reset the hands position to the ZERO position. And continue to push A to put them forward

Push "B"
Reset the chronograph