



# Time measurement & Winding

## Mechanical

### **Accuracy**

Measure within lapse of 10~60 minutes from full winding with ① posture.

#### Posture difference


Measure accuracy in below ①~④ postures.

1) Dial side up

26 o'clock side up

39 o'clock side up

43 o'clock side up



#### ■ To make full-winded

90 / 91	Turn the crown 40 times
82 / 8N	Turn the crown 40 times
6T	Turn the crown 20 times

## ■ Winding direction



