


6T15 6T51



DO NOT set Day between 1:00am - 4:30am



INFORMATION

Time measurement & Winding

Mechanical —


Accuracy

Measure within lapse of $10\sim60$ minutes from full winding with ① posture.

Posture difference

Measure accuracy in below ①∼④ postures.

- ①Dial side up
- 26 o'clock side up
- 39 o'clock side up
- 43 o'clock side up







■ To make full-winded

90 / 91	Turn the crown 40 times
82 / 8N	Turn the crown 40 times
6T	Turn the crown 20 times

■ Winding direction



