

Setting the Time

1 30



INFORMATION

Time measurement & Winding


Mechanical ——

Accuracy

Measure within lapse of $10\sim60$ minutes from full winding with \bigcirc posture.

Posture difference

Measure accuracy in below $1 \sim 4$ postures.



To make full-winded

90/91	Turn the crown 40 times
82 / 8N	Turn the crown 40 times
6T	Turn the crown 20 times

Winding direction

90/91/6T

