





5Y20 5Y30





Battery consumption could be minimum by pulling out the stem





High Hand Ver. 5Y26 5Y36

Time measurement

Accuracy

The unit (gate) time of measurement must be set at "10 sec." and the measurement must be performed in the form of complete watch.

10 sec 10 sec 10 sec

