



8N40







INFORMATION

Time measurement & Winding


• Mechanical ——

Accuracy

Measure within lapse of 10 \sim 60 minutes from full winding with 1) posture.

Posture difference

Measure accuracy in below $1 \sim 4$ postures.



To make full-winded

90/91	Turn the crown 40 times
82 / 8N	Turn the crown 40 times
6T	Turn the crown 20 times

Winding direction

90/91/6T

