



#### 6T28





The option parts

- Casing clamps (082-070)
- Screws (923-140)



#### Gilt Version Available





#### **INFORMATION**

# Time measurement & Winding

## Mechanical —


## Accuracy

Measure within lapse of  $10\sim60$  minutes from full winding with ① posture.

#### Posture difference

Measure accuracy in below  $1 \sim 4$  postures.

- ①Dial side up
- 26 o'clock side up
- 39 o'clock side up
- 43 o'clock side up



# ■ To make full-winded

90 / 91	Turn the crown 40 times
82 / 8N	Turn the crown 40 times
6T	Turn the crown 20 times

## **■** Winding direction

