



### **6T28**





## **INFORMATION**

# Time measurement & Winding

### Mechanical —

## **Accuracy**

Measure within lapse of  $10\sim60$  minutes from full winding with ① posture.

#### **Posture difference**

Measure accuracy in below ① ∼ ④ postures.

- ①Dial side up
- 26 o'clock side up
- ③9 o'clock side up
- 43 o'clock side up











## ■ To make full-winded

90 / 91	Turn the crown 40 times
82 / 8N	Turn the crown 40 times
6T	Turn the crown 20 times

# **■** Winding direction



