





2S60 2S65









Time measurement Accuracy The unit (gate) time of measurement must be set at "10 sec." and the measurement must be performed in the form of complete watch. 10 sec 10 sec 10 sec

