


6P05 6P09 6P22 6P26 6P28 6P89














Time measurement

The unit (gate) time of measurement must be set at "10 sec." and the measurement must be performed in the form of complete watch.

10 sec 10 sec

