


### 9100 9120 9122 9132 9133





#### **INFORMATION**

# Time measurement & Winding

## Mechanical ——


### Accuracy

Measure within lapse of  $10\sim60$  minutes from full winding with ① posture.

#### Posture difference

Measure accuracy in below ①∼④ postures.

- ①Dial side up
- 26 o'clock side up
- 39 o'clock side up
- 43 o'clock side up







#### ■ To make full-winded

90/91	Turn the crown 40 times
82 / 8N	Turn the crown 40 times
6T	Turn the crown 20 times

## **■** Winding direction



