



# JS05 JS15 JS25 JS36


Size <ligne>	12 ½'''
Height <mm>	4.30
Accuracy <per Month>	±20 sec
Battery Life	3 years

\*60 minutes chronograph operation per day




Battery consumption could be minimum by pulling out the stem

Balance Weight <μN·m>	Minute 0.40 Second 0.09 Small 0.02
--------------------------	--

**Featured by Shock Detection**



Original Package	500 pcs
------------------	---------



High Hand Ver.  
JS06  
JS16  
JS26  
JS36

Time measurement Accuracy

The unit (gate) time of measurement must be set at "10 sec." and the measurement must be performed in the form of complete watch.



**Push "A"**  
Start and Stop the chronograph

**Setting the Time**

**Set CHRONOGRAPH hands to reset**

Push A to reset the hands position to the ZERO position. And continue to push A to put them forward

**Setting the Date**

**Push "B"** DO NOT set Date between 9:00pm - 1:00am

Reset the chronograph