


<b>Size</b> <ligne>	13 ½'''
<b>Height</b> <mm>	4.13
<b>Accuracy</b> <per Month>	±20 sec
<b>Battery Life</b>	5 years



Battery consumption could be minimum by pulling out the stem




Small Second



Date

<b>Balance Weight</b> <μN.m>	Second 0.02 Minute 0.40
---------------------------------	----------------------------





<b>Clearance</b>	<p>Clearance changes subject to the glass, case structure, and the length of the hand.</p>
------------------	--------------------------------------------------------------------------------------------

<b>Original Package</b>	500pcs
-------------------------	--------

## Time measurement

### Accuracy

The unit (gate) time of measurement must be set at "10 sec." and the measurement must be performed in the form of complete watch.



Setting the Time

Setting the Date