





Battery consumption could be minimum by pulling out the stem





Clearance

Clearance changes subject to the glass, case structure, and the length of the hand.



Original Package

1,000pcs

Time measurement

Accuracy

The unit (gate) time of measurement must be set at "10 sec." and the measurement must be performed in the form of complete watch.

10 sec 10 sec 10 sec

