



Time measurement & Winding

Mechanical —


Accuracy

Measure within lapse of 10 ~ 60 minutes from full winding with ① posture.

Posture difference

Measure accuracy in below ① ~ ④ postures.

- ①Dial side up
- 26 o'clock side up
- 39 o'clock side up
- 43 o'clock side up



■ To make full-winded

8315 Turn the crown 51 times	S
------------------------------	---

■ Winding direction

