



OS00


Size <ligne>	13 1/2"
Height <mm>	5.10
Accuracy <per Month>	±20 sec
Battery Life	5 years

*60 minutes chronograph operation per day




Battery consumption could be minimum by pulling out the stem

Balance Weight <μN · m>	Minute 0.40 Second 0.11 Small 0.02
----------------------------	--

Featured by Shock Detection



Original Package	500 pcs
------------------	---------



Time measurement

Accuracy
The unit (gate) time of measurement must be set at "10 sec." and the measurement must be performed in the form of complete watch.

Push "A"
Start and Stop the chronograph

Setting the Time
Set CHRONOGRAPH hands to reset

Setting the Date & Day
Push A to reset the hands position to the ZERO position. And continue to push A to put them forward

Push "B"
Reset the chronograph

DO NOT set Day and Date between 9:00pm - 1:00am