



1L40 1L45




18.5 SR621SW

Battery consumption could be minimum by pulling out the stem







The Distance to Small Second 1L40 : 5.0 1L45 : 6.61

Time measurement

Accuracy

The unit (gate) time of measurement must be set at "10 sec." and the measurement must be performed in the form of complete watch.

10 sec 10 sec 10 sec

