

Small Second




7

## Battery consumption could be minimum by pulling out the stem



Second 0.02 Minute 0.40



Original **Package** 

500pcs

## 0T50

## Time measurement

## **Accuracy**

The unit (gate) time of measurement must be set at "10 sec." and the measurement must be performed in the form of complete watch.

10 sec

10 sec

