



JS05 JS15 JS25


Size <ligne>	12 ½"
Height <mm>	4.30
Accuracy <per Month>	±20 sec
Battery Life	3 years

*30 minutes chronograph operation per day





Battery consumption could be minimum by pulling out the stem

Balance Weight <μN·m>	Minute 0.40 Second 0.09 Small 0.02
--------------------------	--

Featured by Shock Detection



Original Package	500 pcs
------------------	---------



High Hand Ver. JS26

Time measurement Accuracy

The unit (gate) time of measurement must be set at "10 sec." and the measurement must be performed in the form of complete watch.

Push "A"
Start and Stop the chronograph

Setting the Time
Set CHRONOGRAPH hands to reset

Setting the Date
Push A to reset the hands position to the ZERO position. And continue to push A to put them forward

Push "B"
Reset the chronograph

DO NOT set Date between 9:00pm - 1:00am