

**GL20** 

**GL30** 

High Hand Ver.

GL26

GL36


Assembled Hour Wheel

Dust Proof Covered Coil

Super Quick Date Adjusting

Easy Assembling on Flat Desk

Battery consumption could be minimum by pulling out the stem




- Time measure

Accuracy

The unit (gate) time of measurement must be set at "10 sec." and the measurement must be performed in the form of complete watch.

10 sec 10 sec



10 sec